

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X

Location ID: 314841

Date: 05/14/2026



Photo # 5157 Entrance to location



Photo # 5159 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X

Location ID: 314841

Date: 05/14/2026



Photo # 5160 Location



Photo # 5164 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X

Location ID: 314841

Date: 05/14/2026



Photo # 5165 Location



Photo # 5166 Location

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X

Location ID: 314841

Date: 05/14/2026



Photo # 5171 Unmarked deadman

Photo # 5172 Debris

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X

Location ID: 314841

Date: 05/14/2026



Photo # 5173 Debris



Photo # 5179 Debris