

Inspection Photos
Counter 1 AB Tank Battery
Spill ID 487481/Remediation No 33683



Photo 1 – Location sign

Photo 2 – Location photo

Inspection Photos
Counter 1 AB Tank Battery
Spill ID 487481/Remediation No 33683



Photo 3 – Open excavation. Downed/inadequate fencing.

Photo 4 – Open excavation. Groundwater/weeds present in open excavation. Fencing down/inadequate.

Inspection Photos
Counter 1 AB Tank Battery
Spill ID 487481/Remediation No 33683



Photo 5 – Fencing down/inadequate around open excavation.

Photo 6 – Fencing down/inadequate around open excavation.

Inspection Photos
Counter 1 AB Tank Battery
Spill ID 487481/Remediation No 33683



Photo 7 – Open excavation. Groundwater/weeds present in open excavation. Fencing down/inadequate.

Photo 8 – Trash. Piping still on location.

Inspection Photos
Counter 1 AB Tank Battery
Spill ID 487481/Remediation No 33683



Photo 9 – Open excavation. Groundwater/weeds present in open excavation. Fencing down/inadequate. Portions of old flowline visible on open excavation (trash).

Photo 10 – Trash on location