

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2026

Submitted Date:

05/18/2026

Document Number:

714300399

FIELD INSPECTION FORM

Loc ID: 473525 Inspector Name: Brown, Kari On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
 Address: 555 17TH STREET SUITE 3700
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	All inspections
Evans, Jacob		jevans@civiresources.com	Civitas Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
493740	SPILL OR RELEASE	CL	04/07/2026		-	Separator base	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 493740/Remediation Project No 43423. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Inspected Facilities

Facility ID: 493740 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: All excavations on location have been backfilled.

Corrective Action: Operator shall provide an updated Form 27 for Remediation #43423 with a workplan and timeline for remediation of Spill ID 493740. Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
	Comment: No E&P waste stored on location.				
	Corrective Action: Operator shall provide all waste manifests as required by Rule 905.b.(3) for oily waste hauled off site for disposal via Form 27				Date: 06/18/2026

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300400	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551727