

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC RIGBY A #3X

Location ID: 315098

Date: 05/14/2026



Photo # 5216 Entrance to location



Photo # 5218 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC RIGBY A #3X

Location ID: 315098

Date: 05/14/2026



Photo # 5220 Wellhead sign lacks public road used to access the well

Photo # 5226 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC RIGBY A #3X

Location ID: 315098

Date: 05/14/2026



**Photo # 5227 Location**