

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 05/12/2026 Document Number: 404655434

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Max Moran Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-4307 Address: P O BOX 173779 Fax: ( ) City: DENVER State: CO Zip: 80217-3779 Email: maxwell\_moran@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 323420 Initial Form 19 or 27 Document number: Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6 County: WELD Field Name: WATTENBERG Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 764985 Facility Name: Reigle 270197 Facility Type: Domestic Well Location: QtrQtr: NENW Sec: 4 Twp: 2N Range: 65W Meridian: 6 County Name: WELD Latitude: 40.173949 Longitude: -104.669679

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 134843 Document Name: Size of file in bytes: 17044 File Name: 2026\_02\_23\_Reigle 270197 Trip Blank SGS ECMC GRO.xlsx SampleType: Matrix: Facility ID: 764985 Sample ID: 676200 Sample Name: Reigle 270197 Sample Date: 02/23/2026 Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA79888-1

Batch ID: 134842 Document Name: Size of file in bytes: 18338 File Name: 2026\_02\_23\_Reigle 270197 Trip Blank SGS  
ECMC.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 764985 Sample ID: 676199 Sample Name: Reigle 270197 Sample Date: 02/23/2026

Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: Accutest Lab Sample ID: DA79888-1

Batch ID: 134846 Document Name: Size of file in bytes: 20518 File Name: 2026\_02\_23\_Reigle 270197 Isotech DG4  
ECMC.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 764985 Sample ID: 676203 Sample Name: Reigle 270197 Sample Date: 02/23/2026

Collection Point: Dom Matrix: GAS Pre Post: Voluntary Post drill

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: ISOTECH Lab Sample ID: 1003977

Batch ID: 134844 Document Name: Size of file in bytes: 32221 File Name: 2026\_02\_23\_Reigle 270197 SGS ECMC.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 764985 Sample ID: 676201 Sample Name: Reigle 270197 Sample Date: 02/23/2026

Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: Accutest Lab Sample ID: DA79887-1

Batch ID: 134845 Document Name: Size of file in bytes: 17045 File Name: 2026\_02\_23\_Reigle 270197 SGS ECMC GRO.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 764985 Sample ID: 676202 Sample Name: Reigle 270197 Sample Date: 02/23/2026

Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: Accutest Lab Sample ID: DA79887-1

Batch ID: 134846 Document Name: Size of file in bytes: 20518 File Name: 2026\_02\_23\_Reigle 270197 Isotech DG4  
ECMC.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 764985 Sample ID: 676204 Sample Name: Reigle 270197 Sample Date: 02/23/2026

Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: ISOTECH Lab Sample ID: 1003977

**Sample Facility Attachment:**

| Facility ID | Attach Num | File Name                                       | Document Name                | File Type |
|-------------|------------|---|------------------------------|-----------|
| 764985      | 404655470  | 2026_02_23_Reigle_270197_Spigot.jpg             | Photographs                  | JPG       |
| 764985      | 404655472  | 2026_02_23_Reigle_270197_Wellhead.jpg           | Photographs                  | JPG       |
| 764985      | 404655473  | 2026_02_23_Reigle_270197_Wellhead_Loc.jpg       | Photographs                  | JPG       |
| 764985      | 404655464  | 2026_02_23_Reigle 270197 SGS.pdf                | Analytical Laboratory Report | PDF       |
| 764985      | 404655447  | 2026_02_23_Reigle 270197 Trip Blank SGS.pdf     | Analytical Laboratory Report | PDF       |
| 764985      | 404655460  | 2026_02_23_Reigle 270197 Isotech DG4 Locked.pdf | Analytical Laboratory Report | PDF       |

|        |           |   |                   |     |
|--------|-----------|---|-------------------|-----|
| 764985 | 404655468 | 2026_02_23_Reigle_270197<br>_PrePostPurge.jpg | Photographs       | JPG |
| 764985 | 404655465 | 2026_02_23_Reigle_27019<br>7_FS_ECMC.pdf      | Field Data Report | PDF |
| 764985 | 404655471 | 2026_02_23_Reigle_270197<br>_Spigot_Loc.jpg   | Photographs       | JPG |

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

**General Comments**

| <b><u>User Group</u></b> | <b><u>Comment</u></b>   | <b><u>Comment Date</u></b> |
|--------------------------|---|----------------------------|
| Environmental Data       | The data submitted by the operator can be accessed through the COGIS data system. | 05/18/2026                 |
| Total: 1 comment(s)      |   |                            |