

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 05/15/2026 Document Number: 404588189

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10758 Contact Person: Javier Martinez Company Name: OGRIS OPERATING LLC Phone: (719) 8596144 Address: PO BOX 53467 Fax: () City: MIDLAND State: TX Zip: 79710 Email: jmartinez@ogrisop.com

Identification Information

API Number: 05 - - ECMC Facility ID: 292547 Initial Form 19 or 27 Document number: Facility Name: HILL RANCH Facility Number: 15-11 Facility Type: PIT Location QtrQtr: NESW Section: 15 Township: 35S Range: 67W Meridian: 6 County: LAS ANIMAS Field Name: PURGATOIRE RIVER Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: OGRIS OPERATING LLC Agent Name: Javier Martinez Title: Environmental Technician Phone Number: 719-8596144 Email: jmartinez@ogrisop.com

Rule 909.J Inspection Information

Date the Pit was Inspected 02/26/2026 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 279157 Facility Name: HILL RANCH 15-11 Facility Type: Coal Bed Methane Well Location: QtrQtr: NESW Sec: 15 Twp: 35S Range: 67W Meridian: 6 County Name: LAS ANIMAS Latitude: 36.995128 Longitude: -104.877390

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 134937 Document Name: Size of file in bytes: 102912 File Name: HR 15-11 ECMC.xls SampleType: Matrix: Facility ID: 279157 Sample ID: 676296 Sample Name: HR 15-11 Sample Date: 02/26/2026 Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2602335-02

Batch ID: 134938 Document Name: Size of file in bytes: 11197 File Name: HR 15-11 Radium ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 279157 Sample ID: 676297 Sample Name: HR 15-11 Sample Date: 02/26/2026

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2602323-02

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. Green Analytical Laboratories, Inc. was added as laboratory for radium samples.	05/19/2026
Environmental Data	RTD - EDD is duplicate of doc # 404588184.	05/15/2026
Environmental Data	RTD - Rule 909j requires Sample Facility ID is for well and Well/Location ID is for related pit.	05/11/2026
Total: 3 comment(s)		