

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

05/14/2026

Document Number:

404588207

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: <u>10758</u>	Contact Person: <u>Javier Martinez</u>
Company Name: <u>OGRIS OPERATING LLC</u>	Phone: <u>(719) 8596144</u>
Address: <u>PO BOX 53467</u>	Fax: <u>()</u>
City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79710</u>	Email: <u>jmartinez@ogrisop.com</u>

Identification Information

API Number: 05 - - ECMC Facility ID: 292540 Initial Form 19 or 27 Document number:

Facility Name: HILL RANCH Facility Number: 17-14 Facility Type: PIT

Location QtrQtr: SESW Section: 17 Township: 35S Range: 67W Meridian: 6

County: LAS ANIMAS Field Name: PURGATOIRE RIVER

Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: OGRIS OPERATING LLC Agent Name: Javier Martinez Title: Environmental Technician

Phone Number: 719-8596144 Email: jmartinez@ogrisop.com

Rule 909.J Inspection Information

Date the Pit was Inspected 02/26/2026

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: <u>265529</u>	Facility Name: <u>HILL RANCH 17-14V</u>	Facility Type: <u>Coal Bed Methane Well</u>
Location: QtrQtr: <u>SESW</u>	Sec: <u>17</u>	Twp: <u>35S</u>
Range: <u>67W</u>	Meridian: <u>6</u>	
County Name: <u>LAS ANIMAS</u>	Latitude: <u>36.993620</u>	Longitude: <u>-104.914260</u>

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: <u>134908</u>	Document Name: <u>Size of file in bytes: 11278</u>	File Name: <u>HR 17-14 Radium ECMC.xlsx</u>
SampleType: <u> </u>	Matrix: <u> </u>	
Facility ID: <u>265529</u>	Sample ID: <u>676267</u>	Sample Name: <u>HR 17-14</u>
Sample Date: <u>02/26/2026</u>		
Collection Point: <u>WellHead</u>	Matrix: <u>WATER</u>	Pre Post: <u>Rule 909.j initial sample</u>
Project Number: <u> </u>	Remediation Number: <u> </u>	Complaint Number: <u> </u>
NOAV Number: <u> </u>		
Inspection Number: <u> </u>	Spill Number: <u> </u>	Laboratory: <u>Green Analytical Laboratories, Inc.</u>
Lab Sample ID: <u>2602323-05</u>		

Batch ID: 134907	Document Name: Size of file in bytes: 100864	File Name: HR 17-14 ECMC.xls
SampleType: _____	Matrix: _____	
Facility ID: 265529	Sample ID: 676266	Sample Name: HR 17-14
Collection Point: WellHead	Matrix: WATER	Pre Post: Rule 909.j initial sample
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2602324-01

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. Green Analytical Laboratories, Inc. was added as laboratory for radium samples.	05/19/2026
Environmental Data	RTD - Rule 909j requires Sample Facility ID is for well and Well/Location ID is for related pit.	05/11/2026
Total: 2 comment(s)		