

Inspection Photos

API: 071-09453

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/18/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the location.



Inspection Photos



Photo 2. Facing toward the wellhead and produced water pit. Pit shows closure in process.



Inspection Photos



Photo 3. Well sign is posted at meter run.

