

Inspection Photos

API: 071-09244

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/18/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road that remains per approved variance..



Inspection Photos



Photo 2. Facing northwest along the road climbing up to the location.



Inspection Photos



Photo 3. Facing northwest at the location which remains flat per approved variance.



Inspection Photos



Photo 4. Facing northwest at the location.



Inspection Photos



Photo 5. Facing west along the fill slope which is stabilized with desirable vegetation.



Inspection Photos



Photo 6. Facing east at the location. The desirable vegetation has established throughout the location.



Inspection Photos



Photo 7. Facing northwest toward the fill slope which is stabilized with desirable vegetation.

