

# Inspection Photos

05/14/2026

Operator: Chevron USA Inc #16700

Location ID: 314518

Inspection Doc: 719201169

Rio Blanco County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 314518



**Photo 1:** Photos showing an overview of the location looking northeast and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 314518



**Photo 2:** Photos showing a thistle rosette and a houndstongue rosette, both present in trace amounts. Weed control is not required at this time; however, ongoing weed monitoring and maintenance is necessary at the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 314518



**Photo 3:** Photos showing wattle maintenance has been performed at the location. The Corrective Action from inspection #719200441 has been resolved.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 314518



**Photo 4:** Rilling and erosion, wattles overtopped with sediment and soil piping occurring at wattles on the northwest portion of the location. Maintenance is required. Comply with 1002.f.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 314518



**Photo 5:** Photos showing an overview of the reclaimed access road leading to the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources