

# ECMC Inspection Photos - KP Kauffman

Location: Facility 5 @ RMFC #9

Date 05/19/2026



May 19, 2026 at 10:51:38 AM  
N 40.0718°, W 104.8951°  
99° E  
Fort Lupton, CO 80621  
Energy and Carbon Management Commission

**KPK Facility 5 @ RMFC 9 spill/ release @ 40.07189, -104.89526**  
**Impacted soils stockpile**

**View looking east from spill/ release point and soils**  
**stockpile toward KPK field personnel working at the eastern**  
**bell hole excavation.**

# ECMC Inspection Photos - KP Kauffman

Location: Facility 5 @ RMFC #9

Date 05/19/2026



Eastern bell hole excavation exposing (1) 4" CS and (1) 2" CS off location flowlines approximately 350' east of spill/ release point @ 40.07180, -104.8940.

Closer view of (2) flowlines exposed in excavation

