

# Final Reclamation Inspection

May 14, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318724

Inspection Document #: 718801706

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LEWIS C. CAMP UNIT D #2  
Location ID: 318724



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: LEWIS C. CAMP UNIT D #2  
Location ID: 318724



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: LEWIS C. CAMP UNIT D #2  
Location ID: 318724



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass and weedy annual vegetation.



**Photo 6.** Photo taken of the well location, facing northwest. See comments under Photo 1.

Inspection Photos  
Location Name: LEWIS C. CAMP UNIT D #2  
Location ID: 318724



**Photo 7.** Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass vegetation.

