

Inspection Photos

Loc# 307407

Operator: OGRIS OPERATING LLC

Inspection Date: 5/21/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the GE 9 compressor station. The compressor has been removed. Unused pipe risers and equipment still remain.



Inspection Photos



Photo 2. It appears the compressor station has been decommissioned. There is no form 27 for decommission and sampling. All unused pipe risers and equipment need to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc#307407 | Date: 5/21/2026

Inspection Photos



Photo 3. There are tanks and risers that don't appear to be needed or in use and must be removed.



Inspection Photos



Photo 4. There is oil stained soil that needs to be cleaned up.

