

Inspection Photos

API: 071-06400

Operator: OGRIS OPERATING LLC

Inspection Date: 5/21/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest at the beginning of the reclaimed access road.



Inspection Photos



Photo 2. Facing south further along the reclamation area. The soils have been tracked seeded, and mulched.



Inspection Photos



Photo 3. Drone aerial photo facing south.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06400 | Date: 5/21/2026

Inspection Photos



Photo 4. Drone aerial photo facing southwest.



Inspection Photos



Photo 5. Drone aerial photo facing southwest toward the location.



Inspection Photos



Photo 6. Drone aerial photo facing northeast overlooking the location.

