

Inspection Photos

API: 071-06399

Operator: OGRIS OPERATING LLC

Inspection Date: 5/21/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast at the beginning of the reclaimed access road. There are noxious weeds emerging at red arrow that need herbicide control.



Inspection Photos



Photo 2. There are Canada thistle plants that will need herbicide weed control.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 3. Facing southeast along the reclaimed access road. The vegetation is well established.



Inspection Photos



Photo 4. There are numerous noxious weeds along this area that need to be controlled.



Inspection Photos



Photo 5. Facing south along the reclaimed access road.



Inspection Photos



Photo 6. Facing south toward the reclaimed location.



Inspection Photos



Photo 7. There are numerous Plumeless thistle stems from last year growth. Noxious weeds will need to be controlled at the location.

