

Inspection Photos
Location Name: UPRR 43 Pan Am B8
Location ID: 318429



Photo 1 Location access road gates are locked without KP Kauffman lock in the chain.

Photo 2 Location access road.