

Final Reclamation Inspection

May 4, 2026

Operator: FOUNDATION ENERGY MANAGEMENT LLC -
10112

Location ID: 318847

Inspection Document #: 718801683

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ELLIOTT #6-27
Location ID: 318847



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities do not appear to have taken place at the well location. Bare ground and gravel were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: ELLIOTT #6-27
Location ID: 318847



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: ELLIOTT #6-27
Location ID: 318847



Photo 5. Photo taken of the access road to the location, facing southwest. Photo illustrates that final reclamation activities have not taken place along the access road.



Photo 6. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities do not appear to have taken place at the tank battery as bare ground and gravel were observed across the location.

Inspection Photos
Location Name: ELLIOTT #6-27
Location ID: 318847



Photo 7. Photo taken of the tank battery location, facing south. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing west. See comments under Photo 6.

Inspection Photos
Location Name: ELLIOTT #6-27
Location ID: 318847



Photo 7. Photo taken of ground cover at the tank battery location. Photo illustrates bare ground and gravel.



Photo 8. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass vegetation.

