

# Inspection Photos

05/20/2026

Operator: Wesco Operating Inc #95520

Location ID: 312871

Inspection Doc: 719201182

Moffat County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 3:** Photo showing stockpiled soils around the open excavation appear to lack adequate fencing and stormwater protections; implementation and/or maintenance of wildlife protections and stormwater BMP's is required.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 4:** Photos showing the utility pole (yellow arrow) and unused equipment/supplies remain throughout the location. Utility equipment will be removed in 2026; all additional surface equipment (green arrow) requires removal by 4/1/2027.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 5:** Photos showing trash/debris is scattered throughout the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 6:** Photos showing the upper portion of the cut slopes are predominantly bare; exposed roots indicate active degradation. Check dams have not yet been installed and additional stormwater controls may be necessary to stabilize the slopes. Comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 7:** Photos showing the edges of the pad are primarily composed of Great Basin wildrye and sagebrush; hoary cress, and houndstongue, both a noxious weed, are present in tertiary amounts. Weed control is not required at this time; however, ongoing weed monitoring and maintenance is necessary.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 8:** Photos showing additional examples of trash/debris that requires removal from the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 9:** Houndstongue, a noxious weed, is present in tertiary amounts along the margins of the pad.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 10:** Photos showing examples of the nearby reference area, directly northeast of the location. Scrub oak is dominant. Cheatgrass and hoary cress are present in the understory, along with native grasses and forbs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312871



**Photo 11:** Photo showing the access road leading to the location. Erosion and rilling is occurring in some place along the road; maintenance is recommended.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources