

Inspection Photos

05/20/2026

Operator: Wesco Operating Inc #95520

Location ID: 312988

Inspection Doc: 719201199

Moffat County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 2: Photos showing an overview of the location looking east and west, respectively. The location has been pocked. Operator indicates that they will provide documentation from the BLM regarding final reclamation at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 3: Photos showing the plugged & abandoned well markers at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 4: Photos showing hoary cress and weedy annual mustard species that are present in secondary to tertiary amounts throughout the location. Weed control is required.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 5: Photos showing the access road leading to the location; the Operator has noted that the access road will be reclaimed and reseeded pursuant to 1004 series rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 6: Photos showing perimeter fencing is down in some places; maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 7: Photos showing an earthen berm around the perimeter of the location. Operator indicates that they will provide documentation from the BLM regarding final reclamation at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312988



Photo 6: Photos showing an example of the nearby reference area, directly north of the location. The reference area is dominated by big sagebrush.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources