

Inspection Photos

API: 011-06173

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/26/2026

County: BENT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. The cattle guards and posts have not been removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 2. Facing west at the location. The abandoned pipe risers have not been removed.



Inspection Photos



Photo 3. Facing north at the location. This area has not been reclaimed and consists of undesirable weeds.



Inspection Photos



Photo 4. View of ground cover shows bare soil and undesirable weeds.



Inspection Photos



Photo 5. Facing southwest at the location. This area has not been reclaimed and consists of undesirable weeds.



Inspection Photos



Photo 6. This pipe riser has no signage or LOTO.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:011-06173 | Date: 5/26/2026