

Inspection Photos

API: 061-06804

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/26/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Center of the location facing north. The location is not reclaimed and soils are mostly bare of vegetation.



Inspection Photos



Photo 2. Center of the location facing west. The location is not reclaimed and soils are mostly bare of vegetation.



Inspection Photos



Photo 3. Center of the location facing south. The location is not reclaimed and soils are mostly bare of vegetation.



Inspection Photos



Photo 4. Center of the location facing east. The location is not reclaimed and soils are mostly bare of vegetation.



Inspection Photos



Photo 5. Facing toward the surrounding undisturbed reference area.

