

Inspection Photos

05/20/2026

Operator: Wesco Operating Inc #95520

Location ID: 312881

Inspection Doc: 719201188

Moffat County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312881



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312881



Photo 2: Photos showing an overview of the location looking east and west, respectively. The Operator plans to retain the access road through the location.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312881



Photo 3: Cut slopes at the location are bare; active erosion was occurring while the inspector was at the location. Stabilization is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312881



Photo 4: Photos showing the southern reclaim area. Hoary cress and cheatgrass, both noxious weeds, are present in tertiary amounts along the edges of the pad.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312881



Photo 5: Photos showing utility equipment that is present at the location. The Operator plans to remove utility equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources