

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



Location – Photo #03992



Location – Photo #03991

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



May 21, 2026 at 15:07:08
+39.579929,-108.190683
Parachute CO 81635
United States



May 21, 2026 at 15:12:16
+39.580170,-108.192084
Parachute CO 81635
United States

Location – Photo #03979

Location – Photo #03994

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



Location – Photo #03995



Location – Photo #03996

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



Debris – Photo #03980



Debris – Photo #03983

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



Debris – Photo #03984



Debris – Photo #03987

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



Unsecured Separator/Wildlife Entry Hazard – Photo #03990



Debris – Photo #04002

Audit Photos

Location Name: QB ENERGY OPERATING LLC, LATHAM/O29 696

Location ID: 335836

Date: 5/21/2026



Debris – Photo #04003



Unplugged Line – Photo #04006