

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 05/08/2026 Document Number: 404651622

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 75000 Contact Person: Carol Byrd Company Name: BYRD* CAROL W TRUSTEE OF CAROL W BYRD TRUST Phone: (214) 205-0387 Address: 8163 E 131 RD Fax: () City: WETUMKA State: OK Zip: 74883-6227 Email: cwbyrd@oilandgasroyalties.com

Identification Information

API Number: 05 - - ECMC Facility ID: 102612 Initial Form 19 or 27 Document number: Facility Name: LYLE CHANDLER Facility Number: Facility Type: PIT Location QtrQtr: NESE Section: 10 Township: 2N Range: 49W Meridian: 6 County: WASHINGTON Field Name: HYDE Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc Agent Name: Lauren Glazer Title: Consultant Phone Number: 800-288-2657 Email: lglazier@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 03/30/2026 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 234894 Facility Name: LYLE CHANDLER 1 Facility Type: Oil and Gas Well Location: QtrQtr: NESE Sec: 10 Twp: 2N Range: 49W Meridian: 6 County Name: WASHINGTON Latitude: 40.154260 Longitude: -102.833370

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 134809 Document Name: EDD File Name: 2026_0330_Lyle Chandler 909J_CGRS EDD AA46704.xlsx Sample Type: Matrix: Facility ID: 234894 Sample ID: 676165 Sample Name: Lyle Chandler Sample Date: 03/30/2026 Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Elevation Diagnostics Lab Sample ID: AA46704

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
234894	404651623	2026_0330_Lyle Chandler 909J_AA46704.pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
676165	121-07036	LYLE CHANDLER 1	Rule 909.j subsequent sample

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	05/29/2026

Total: 1 comment(s)