

Select Run#

Battery (optional)

Report Month

Run# 8

PETE MONTOYA B

April - 2026

### Edit PETE MONTOYA B AVO Inspection

Emissions Observed (Y / N)

Yes

No

Within 1000 ft of Occupied Structure (Y / N)

Yes

No

Emission Observation Description

Crack in water tank

Date Observed

03/13/2026

Reliable information (Y / N)

Yes

No

Corrective Actions Taken

Water leg still shut in

1st Repair Attempt Date

03/13/2026

Date of Repair

Facility Shut In (Y / N)

Yes

No