Remediation
Soil & Groundwater Sampling Fieldsheet

* * * Facility Information * * *

O&G Site Name	Williams (31-11) #7	**Client**	Citation	REM Project #	CIT.CO.1054
Weather	88F, Smoky	**Surface Flow Direction**	East		
API/TB#		**Liner Present?**	No	**Site Coordinates**	38.934558 N, 103.078047 W
Location Directions	At the intersection of CR Z and CR 4 5/10 turn S, when the road ends take a left heading E ~300 ft until you see a two track N.				
Sample Date	3/26/2026	**Sampler(s)**	DM		

Soil Sampling

Soil Sample ID	Time	Date	Lab?	PID (ppm)	Location Description	Staining	Color / Lithology
BKG03@2'	11:30	3/26/2026	Yes	0.6	~150ft W of pad	No	Tan SANDY LOAM
BKG03@5'	11:40	3/26/2026	Yes	0.6	~150ft W of pad	No	Tan SANDY LOAM
BKG04@2'	11:50	3/26/2026	Yes	0.9	~150ft N of pad	No	Tan SANDY LOAM
BKG04@5'	12:00	3/26/2026	Yes	1.3	~150ft N of pad	No	Tan SANDY LOAM

Groundwater Sampling

Groundwater Sample ID	Time	Date	Depth To Water (feet)	Associated Soil Sample ID	Sheen?

Decon Methods: Alconox & DI Water

Site Comments: Site is starting to be grown over, there is a two-track to get to the pad. Took BG samples.