



Site Closure Soil Sampling Photographic Log

**Williams 31-11 #7
Remediation Project #: 31674**



WGS84 38.93429,
±38ft -103.07781

ft
±8ft 4803

°T
±12 NW313



Description:
BKG02 Soil sample
location

27Jun24 14:08 / Ad-hoc
Wild Horse CO 80862, United States © 27-Jun-24 14:08:14

Network: Mar 26, 2026 at 11:45:44 MDT
N 38.934506°, W 103.078764°
75° E
Wild Horse CO 80862
United States
Remark: Williams 31-11 #7
BKG03@2' 5'

BKG03@2' & 5'

X



Description:

BKG03@2'

PID=0.6

BKG03@5

PID=0.6



Description:

BKG04@2'

PID=0.9

BKG04@5

PID=1.3