

# Inspection Photos

May 22nd, 2026

Operator: Forest Oil Corporation

Location ID: 322122

Inspection Document #: 714003641

County: Dolores

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Huskey A1

May 21, 2026  
236° SW



**Photo 1.** Field not yet planted.

