

Inspection Photos

May 22nd, 2026

Operator: Mobil Oil Corporation

Location ID: 381598

Inspection Document #: 714003642

County: Dolores

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Spargo 1-23



Photo 1. 2023 NAIP Imagery of the well pad (highlighted in blue) and associated access road (highlighted in red). Note: portion of access road highlighted in green predates oil and gas location and does not require reclamation.

Inspection Photos
Location Name: Spargo 1-23

May 21, 2026
304° NW



Photo 2. View of associated access taken from the well pad access point facing northwest. Note: access road has not been reclaimed per 1004 rules.

Inspection Photos
Location Name: Spargo 1-23



Photo 3. View of well pad project area taken from the northern edge facing center. Note: Location sign remains on location. Vegetation establishment along location cut slopes and within portions of the project area have not met 1004 standards.

Inspection Photos
Location Name: Spargo 1-23



Photo 1. Anchor cable remains on the western edge of the project area.

