

# Inspection Photos

API:071-06263

Operator: OGRIS OPERATING LLC

Inspection Date: 6/1/2026

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing south at the location. The HR 33-4 meter shed has not been removed. The well was plugged and abandoned on 1/25/2005.



## Inspection Photos



**Photo 2.** Facing west. The associated pit of the Hill Ranch 33-4 has not been backfilled and reclaimed.



## Inspection Photos



**Photo 3.** Facing northwest. The HR 33-4 plugged well was located to the south of the active HR 33-4X wellsite.

