

Inspection Photos

API:071-08248

Operator: OGRIS OPERATING LLC

Inspection Date: 6/1/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-08248 | Date: 6/1/2026

Inspection Photos



Photo 2. This culvert outlet is filled in and needs maintenance.



Inspection Photos



Photo 3. There is a dripping leak at the wellhead that needs to be fixed.

