

Inspection Photos

API:071-06912

Operator: OGRIS OPERATING LLC

Inspection Date: 6/1/2026

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06912 | Date: 6/1/2026

Inspection Photos



Photo 2. Facing east along the fil slope which is stabilized with vegetation.



Inspection Photos



Photo 3. Facing west at the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06912 | Date: 6/1/2026

Inspection Photos



Photo 4. There is oily fluid that spilled on the ground and oily fluid in the engine skid that needs to be cleaned up..

