

Inspection Photos  
Location Name: Milton H. Nelson F #1  
API #: 05-123-10469



Photo 1: Location from entrance

Photo 2: Wellhead sign

Inspection Photos  
Location Name: Milton H. Nelson F #1  
API #: 05-123-10469



Photo 3: Overgrown, undesirable vegetation.

Photo 4: Overgrown, undesirable vegetation.

Inspection Photos  
Location Name: Milton H. Nelson F #1  
API #: 05-123-10469



Photo 5: Overgrown, undesirable vegetation



Photo 6: Unoccupied nest

**Inspection Photos**  
**Location Name: Milton H. Nelson F #1**  
**API #: 05-123-10469**



**Photo 7: location of alleged released emissions**