

Inspection Photos

May 27th, 2026

Operator: Highpoint Operating
Corporation

Location ID: 313626

Inspection Document #: 714003657

County: Montezuma

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gray 13H-15-37-17



Photo 1. 2024 NAIP imagery of the well pad (highlighted in blue) and associated access road (highlighted in red).



Inspection Photos
Location Name: Gray 13H-15-37-17



Photo 2. View of well pad and associated access road taken with a drone during the time of the inspection from the southern edge facing north. Note: stunting observed at well pad compared to reference areas, see photo 4.

May 28, 2026
314° NW



Photo 3. Ground view of the well pad taken from southern edge facing center.

Inspection Photos
Location Name: Gray 13H-15-37-17



Photo 4. Well pad sample crop (left) and reference area crop (right) taken during the time of the inspection. Sample shows that project area has stunted crop compared to adjacent reference areas.

