

## Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5780 Entrance to location



Photo # 5781 Weeds/undesirable plant species presents a potential fire hazard

## Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



**Photo # 5783 Weeds/undesirable plant species presents a potential fire hazard**



**Photo # 5784 Weeds/undesirable plant species presents a potential fire hazard**

# Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5801 Tank battery/Weeds/undesirable plant species presents a potential fire hazard

Photo # 5802 Location

# Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5803 Production tank label lacks operator name & contact number

Photo # 5814 Location

# Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5815 Location



Photo # 5816 Location

# Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5792 Staining



Photo # 5793 Staining

# Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5794 Staining



Photo # 5798 Staining

## Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5804 Staining



Photo # 5806 Staining

## Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



Photo # 5808 Open ended load line



Photo # 5810 Weeds/undesirable plant species presents a potential fire hazard

## Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



**Photo # 5811 Weeds/undesirable plant species presents a potential fire hazard**



**Photo # 5818 Erosion & sediment migration with staining/insufficient BMP's**

## Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON #17-4

Location ID: 315470

Date: 05/28/2026



**Photo # 5825 Erosion & sediment migration**



**Photo # 5827 Erosion & sediment migration with staining/insufficient BMP's**