

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 1 wellhead

Pic 2 gas leaking from packing on wellhead

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 3 Wellhead sign

Pic 4 weeds unmanaged on location

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 5 GMR, Separator

Pic 6 Unable to access calibration card due to wasp nest on GMR

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 7 separator

Pic 8 horizontal separator

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 9 Separators

Pic 10 Tanks

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 11 tank sign

Pic 12 tanks, weeds unamaged on location

Inspection Photos
Location Name: Lucy 14-26
Location ID: 318972



Pic 13 open top tank

Pic 14 open top tank